

Complaint Number	Date/Time Received	Nature of Complaint	Response
646	16/02/2024, 12.53pm	Blast Vibration	Complaint received via the Community Hotline. Complainant discussed blast vibration from the Mount Pleasant Operation. Pattern 14.6.PF2C was initiated in South Pit on the 16th of February at 12.42pm. At the time of blasting, the A-PF4 meteorological station recorded a 1 hourly rolling wind direction of 175 degrees SE with a 1 hourly rolling wind speed of 3.6 m/s. The compliance monitor B-VO2 monitor (the most representative of private residences) recorded 0.49 mm/s and 97.9 DBL for vibration and overpressure. All vibration and overpressure monitors were within the compliance limits of 10 mm/s and 120 DBL.
647	19/02/2024, 8.19pm	Lighting	Complaint received via the Community Hotline. Complainant discussed lighting from the Mount Pleasant Operation. When the complaint was received an investigation was carried out in which pit cameras and operations were reviewed on the night of the complaint. All lights viewed were found to be facing in pit.