

Complaint Number	Date/ Time Received	Nature of Complaint	Response
419	5/08/2020,	Odour	Complaint received via the Community Hotline. Discussed odour from the Mount Pleasant Operation. Upon receiving the complaint, an inspection of the operation was carried out by the OCE and a review of the pit cameras was undertaken by the Thiess Environment & Community Superintendent and an offsite inspection was undertaken by the Thiess Environment & Community Officer, where it was identified that smoke was coming from the Pit E RL185 dump. At 5:30pm DZ1665 began the task of covering the heated material. The capping task was completed at 6:20pm. Heated material within the active working areas are managed in accordance with the Mount Pleasant Spontaneous Combustion Principle Hazard Management Plan.
420	6/08/2020, 3.46pm	Blasting	Complaint received via the Community Hotline. Discussed blasting from at the Mount Pleasant Operation. On the 5th August 2020, Patterns 23-25.2.BR2C.2_17-18.3.BR2C were initiated together in Pit B & C at 15:44. At the time of blasting the A-PF4 meteorological station recorded a 1 hourly rolling wind direction of 322 degrees NW with a hourly rolling wind speed of 1.3m/s. All vibration and overpressure monitors were well within the compliance limits.