

Complaint Number	Date/Time Received	Nature of Complaint	Response
446	9/12/2020, 2.02pm	Dust	Complaint received via the Community Hotline regarding dust from a recent blast at the Mount Pleasant Operation. Pattern 38.2.BR2C was fired in Pit E at 1:01 pm. At the time of blasting the A-PF4 meteorological station recorded light wind conditions with a 5-minute average wind speed of 1.6 m/s and wind direction of 198 degrees (SW). The post blast emissions were observed to head in a Westerly direction (away from Muswellbrook) and fully dispersing within the Pit. No post blast emissions left the EPL or DA boundary.
447	23/12/2020,	Blast	Complaint received via direct SMS to the External Relations Managers mobile phone. Pattern 31.2.WN2C was fired in Pit D at 1:50 pm, At the time of blasting the A-PF4 meteorological station recorded a wind direction of 142°(SE) with a 5-minute wind speed of 3.8 m/s. The B-VO2 compliance blast monitor (most representative of the residence) recorded vibration of 0.76 mm/s and overpressure of 109.4 dB. All vibration and overpressure compliance monitors were well within the compliance limits.