

Complaint Number	Date/Time Received	Nature of Complaint	Response
601	17/2/23, 9.59am	Noise	Complaint received via the Community Hotline. Complainant discussed noise from the Mount Pleasant Operation. Mining operations are regularly monitored and altered to minimise the impacts from noise. Upon receipt of the complaint an inspection of the operation was undertaken by the OCE, No noise issues were identified. This was also confirmed by the Environment and Community Superintendent, who was undertaking a Rehabilitation inspection at the time of the complaint. Meteorological conditions recorded at the A-PF2 were valid with a wind direction of 153° (SE) and a wind speed of 1.4m/s recorded. No noise alarms were triggered prior to the complaint at Site 2/3.
602	28/2/23, 8.00pm	Lighting	Complaint received via the Community Hotline. Complainant discussed lighting from the Mount Pleasant Operation. The lighting plants on the 230 RL Central and 230 RL North dump were inspected by the OCE and found to be positioned correctly pointing towards the west away from Muswellbrook.
603	28/2/23, 10.44pm	Lighting	Complaint received via the Community Hotline. Complainant discussed lighting from the Mount Pleasant Operation. The lighting plants on the 230 RL Central and 230 RL North dump were inspected by the OCE and found to be positioned correctly pointing towards the west away from Muswellbrook.